

MODELS LC26SD1EK LC32SD1EK LC37SD1EK LC42SD1EK

SYMPTOM When teletext selected no text appears or message “Teletext not available” appears.

CAUSE Software issues with IC3002 VCT.

ACTION Update software for IC3002 to latest version.

Sharp Electronics (UK) Limited

Reference – SP072000x
Revision - 1

White – Carry out as required
Yellow – Carry out as required and whenever the unit comes in for service
Red – Carry out on all units